


Elite Model 900 / 900XM



Humidifier Replacement Parts

Item	Qty. Req'd	GFI No.	Description of Part	LIST / RETAIL
				PRICE EACH
1	1	7940	900-1 Chasis	\$82.97
2	1	7561	900-9 Nozzle	\$3.30
3	1	7562	900-10 Spout	\$3.27
4	1	7588	GA4266 Distributor Tube	\$7.99
5	1	7221	GA4040 Solenoid Valve 24V	\$70.20
6	1	7564	GA4004 Strainer Screen	\$4.31
7	1	7566	P102 Compression Sleeve (copper)	\$4.20
		7568	P190 Compression Sleeve (plastic)	\$3.83
8	2	7565	P101 Compression Nut	\$4.20
9	1	7567	P189 Brass Insert Tube	\$3.83

Item	Qty. Req'd	GFI No.	Description of Part	LIST / RETAIL
				PRICE EACH
10	2	7941	900-40 Pad Rail	\$4.53
11	1	7919	GA19 Vapor Pad	\$13.00
12	1	7570	900-15 Distributor Trough	\$15.03
13	1	7571	900-14 Drain Pan	\$4.00
14	1	7580	GA4231 Orifice (Yellow)	\$1.43
15	1	7568	P190 Compression Sleeve	\$3.83
16	1	7078	747-38 Tubing Kit (Available)	\$11.00
17	1	7572	900-11 Damper Knob	\$3.64
18	1	7573	900-28 Damper Disk	\$11.70
19	1	7576	900-2 Side Panel	\$85.36
20	1	7577	900-13 Cover	\$52.34
21	1	7578	900-16 Name Plate	\$10.00

2% 10th Prox. Net 30 Days. F.O.B. Novi, Michigan