



Sealed Unit Parts Co. Inc.


www.supco.com

info@supco.com



Replacement Ice makers

RIM597 Replacement for Whirlpool® 2198597




Designed to replace Whirlpool®, Kenmore®, Kitchenaid®, in 2000 different models. The RIM597 replaces part numbers: 2198597, 2198678, 626663, W10122502, W10190960

Offering the modular icemaker with heavy duty rake and extra wide stripper board. Excellent choice to replace the Whirlpool® 2198597 in the door icemaker as well as Kenmore® / Coldspot® [models with starting prefix 106 or 198]. Check model number verify application.

RIM900 Bare Icemaker

Universal replacement for all modular style icemakers.



This is the bare icemaker itself, complete with cover. Designed to use the existing modular icemaker wiring harness, this icemaker will replace most of the 120 VAC modular icemakers on the market today. Replaces hundreds of different modular icemakers on tens of thousands of refrigerators. Brands include: Kenmore®, Whirlpool®, Admiral®, Amana®, Crosley®, Magic Chef®, Maytag®, SubZero® and many others.

Using the existing wiring harness on the refrigerator, this icemaker will replace: 8114, 0056504, 0056599, 0056605, 0056606, 311155, 312578, 312738, 10563707, 10563708, 61005508, 67001263, 312739, 312740, 480616, 480617, 4210317, 4211173, 4317943, 10549201, 482014, 482015, 482016, 482017, 482018, 482019, 482020, 482394, 482433, 482990, 625601, 625603, 61005508A, 68111-1, 68972-1, 68972-4, 625610, 625611, 625622, 625625, 625653, 625656, 625660, 626002, 626201, 626237, 626366, 626461, 626489, 626608, 626609, 626626, 626636, 626670, 627572, 797991, 68972-4, 95091-1, 95098-1, 95109-1, 833701, 840991, 853522, 941554, 978552, 978553, 978556, 1105299, D7767601, D7824701, D7824702, D7824703, D7824704, D7824705, D7824705Q, D7824706, D7824706Q, R0154025, R0156628, R0156629, R0156629, R0156669, R0161059, R0161061, R0183135, R0194462, R0194666, R0950064, W10122496, W10122519, W10190952., W10190978., Y689724.