


# Humidifier Replacement Parts

## Parts Price Schedule



# Models 747 and 747L



| Item | Qty. Req'd | Part No. | Description of Part              | LIST / RETAIL |
|------|------------|----------|----------------------------------|---------------|
|      |            |          |                                  | PRICE EACH    |
| 1    |            | 7108     | 727-4 Drum assembly              | \$62.33       |
| 2    | 1          | 7107     | 727-12 Evaporator sleeve 8 3/4"W | \$21.71       |
| 3    | 1          | 7157     | P188 Retainer clip               | \$1.33        |
| 4    | 1          | 7105     | 727-7 Drum shaft                 | \$11.50       |
| 5    | 2          | 7125     | 727-5 Drum end                   | \$15.66       |
| 6    | 1          | 7069     | 747-1 Water pan                  | \$98.33       |
| 7    | 1          | 7073     | 747-26 Humidity control assembly | \$73.33       |
| 8    | 1          | 7129     | 45-1 Drum bearing                | \$1.50        |
| 9    | 1          | 7070     | 747-5 Quick drain                | \$11.00       |
| 10   | 1          | 7079     | 747-25 115V motor assembly (747) | \$63.45       |
|      | 1          | 7082     | 747-28 24V motor assembly (747L) | \$53.23       |
| 11   |            | 7074     | 747-29 Float valve assembly      | \$46.24       |
| 12   | 1          | 6001     | 975-3 Orifice nut                | \$.75         |
| 13   | 1          | 7075     | 747-35 "L" tube assembly         | \$11.00       |
| 14   | 1          | 7076     | 747-11 Valve washer              | \$.90         |
| 15   | 1          | 7123     | 727-8 Splash guard               | \$2.00        |
| 16   | 1          | 7156     | P187 Compression union           | \$1.50        |
| 17   | 1          | 6005     | 975-6 Valve shield               | \$.99         |
| 18   | 1          | 7122     | 727-24 Orifice fitting           | \$6.50        |
| 19   | 1          | 6026     | P118 Cotter pin                  | \$.95         |
| 20   | 1          | 6004     | 975-1 Valve seat                 | \$.50         |
| 21   | 1          | 7121     | 727-34 Float arm                 | \$5.00        |
| 22   | 1          | 7119     | 727-32 Float block               | \$8.50        |

| Item                   | Qty. Req'd | Part No. | Description of Part   | LIST / RETAIL |
|------------------------|------------|----------|---|---------------|
|                        |            |          |   | PRICE EACH    |
| <b>PARTS NOT SHOWN</b> |            |          |   |               |
|                        | 1          | 7083     | 747-36 24V transformer (747L)<br>(10 VA)                                      | \$22.00       |
|                        | 1          | 7080     | 747-14 115V power cord (747)  | \$15.00       |
|                        | 1          | 7078     | 747-38 Water supply tubing kit  | \$11.00       |
|                        | 1          | 8022     | 800-UST Self-tapping saddle valve kit   | \$11.00       |
|                        | 1          | 7127     | 727-48 Lead wire assembly<br>(10' of low voltage wire w/<br>Terminals - 747L) | \$8.82        |
|                        | 6          | 7043     | 1099-9 Thumb nut  | \$2.00        |
|                        | 1          | 7072     | 747-7 Mounting frame  | \$28.33       |
|                        | 1          | 7155     | P185 Quick drain clamp  | \$4.00        |
|                        |            | 8035     | 8035 Humidex tablets  | \$12.00       |

2% 10th Prox. Net 30 Days. F.O.B. Novi, Michigan

General Filters Inc. 43800 Grand River Novi, Michigan 48375-1115 Toll Free (866) 476-5101 Fax (248) 349-2366  
www.GeneralAire.com

Humidifier Replacement Parts