


Elite Model 1000 / 1000XM



Humidifier Replacement Parts

Item	Qty. Req'd	GFI No.	Description of Part	LIST / RETAIL
				PRICE EACH
1	1	7561	900-9 Nozzle	\$3.30
2	1	7562	900-10 Spout	\$3.27
3	1	7580	GA4231 Orifice (Yellow)	\$1.43
4	1	7568	P190 Compression Sleeve	\$3.83
5	2	7565	P101 Compression Nut	\$4.20
6	1	7563	GA4235 Distributor Tube	\$9.97
7	1	7567	P189 Brass Insert Tube	\$3.83
8	1	7566	P102 Compression Sleeve (copper)	\$4.20
		7568	P190 Compression Sleeve (plastic)	\$3.83
9	1	7564	GA4004 Strainer screen	\$4.31
10	1	7222	GA4045 Solenoid Valve	\$81.20

Item	Qty. Req'd	GFI No.	Description of Part	LIST / RETAIL
				PRICE EACH
11	2	7941	900-40 Pad Rail	\$4.53
12	1	7919	GA19 Vapor Pad	\$13.00
13	1	7571	900-14 Drain Pan	\$4.00
14	1	7570	900-15 Distributor Trough	\$15.03
15	1	7582	GA4247 Fan Blade	\$26.16
16	1	7584	GA4237 Motor	\$111.55
17	1	7578	900-16 Name Plate	\$10.00
18	1	7579	1000-11 Wiring Harness	\$13.50
19	1	7586	GA4238 Relay Circuit Board	\$64.36
20	1	7346	1137-31 Power Supply Cord	\$15.00
21	1	7950	950-1 Chasis	\$95.99
22	2	7583	1000-1 Baffle	\$21.77
PARTS NOT SHOWN				
	1	7585	1000-13 Front Cover	\$75.87

2% 10th Prox. Net 30 Days. F.O.B. Novi, Michigan

General Filters Inc. 43800 Grand River Novi, Michigan 48375-1115 Toll Free (866) 476-5101 Fax (248) 349-2366
www.GeneralAire.com