




Sealed Unit Parts Co. Inc.

www.supco.com
info@supco.com




Replacement Icemakers

**RIM500 Replacement for Whirlpool® 4211173, 4317943,
Also replaces icemaker only on older Admiral® models.**



Designed to replace Kenmore® [made by Whirlpool® prefix 106], Whirlpool® universal modular replacement includes wiring harness for old Admiral® models as well. Replaces: 4317943, 4210317, 4211173, 480616, 480617, 482014, 482015, 482016, 482017, 482018, 482019, 482020, 482394, 482433, 482990, 625601, 625603, 625610, 625611, 625622, 625625, 625653, 625656, 625660, 626002, 626201, 626237, 626366, 626461, 626489, 626608, 626609, 626626, 626636, 626670, 627572, 68972-4, 797991, 8114, 833701, 978552, 978553, 978556, W10122496, W10190952.

RIM501 Replacement for Amana® 1110702A and D7824706Q



Designed to replace Amana® 1110702A kit and the bare icemaker D7824706. Using the harness this icemaker replaces part numbers: 1110702A, 1110701A, D7567102, D7567105, D7567105A, D7621301, D7621305, D7621307, D7621310, IC-3, IC3, IC3H, IC3K, IC3N, IC3Q, IC4N, R0175023.

The RIM501 using your existing harness replaces hundreds of modular icemakers on Kenmore®, Whirlpool®, Admiral®, Amana®, Crosley®, Magic Chef®, Maytag®, SubZero® and many others.

Replaces: D7824705Q, 0056504, 0056599, 0056605, 0056606, 0311155, 0312578, 0312738, 0312739, 0312740, 10549201, 10563707, 10563708, 61005508, 61005508A, 67001263, 68111-1, 68972-1, 68972-4, 95091-1, 95098-1, 95109-1, D7767601, D7824701, D7824702, D7824703, D7824704, D7824705, D7824706, D7824706Q, R0154025, R0156628, R0156629, R0156669, R0161059, R0161061, R0167201, R0183135, R0194462, R0194666, R0950064, Y689724, W10122519, W10190978.